

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

 $\begin{array}{c} {\rm JON~M.~HUNTSMAN,~JR.} \\ {\rm \it Governor} \end{array}$

GARY R. HERBERT Lieutenant Governor

Representative	es Present During the Inspection:	
OGM	Pete Hess Environmental Scientist III	
Company	Scott Dimick Superintendent	

Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Monday, December 12, 2005
Start Date/Time:	12/12/2005 1:30:00 PM
End Date/Time:	12/12/2005 4:00:00 PM
Last Inspection:	Monday, November 07, 2005

Inspector: Pete Hess, Environmental Scientist III

Weather: Clear; sunny and cool. 40's F.
InspectionID Report Number: 810

Accepted by: whedberg 12/21/2005

Permitee: ANDALEX RESOURCES INC TOWER DIVISION
Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

100.00	Total Permitted	
63.70	Total Disturbed	
	Phase I	
	Phase II	
	Phase III	

Mineral Ownership Types of Operations

✓ Federal	☐ Underground
State	Surface
County	✓ Loadout
Fee	✓ Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division on December 8, 2005 that the third quarter, 2005 water monitoring information for the Wildcat Loadout was in the pipeline and acceptable for uploading. This information includes UPDES monitoring for the sites six sediment ponds as well as the four creek monitoring points in Wildcat Wash. This meets the requirement stated in Attachment "A", Special Permit Condition of the current State permit issued by the DOGM.

The Division Order for the Wildcat Loadout permit area remains pending.

Inspec	tor's	Signa	ture
--------	-------	-------	------

Date Wednesday, December 14, 2005

Pete Hess, Environmental Scientist III
Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Monday, December 12, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.	a Roads: Construction, Maintenance, Surfacing	✓			
16.	o Roads: Drainage Controls	✓			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Monday, December 12, 2005 Page 3 of 3

2. Signs and Markers

The Permittee has installed additional SPEED LIMIT / 5 MPH signs along the primary haul road designated as PR-6 (See Plate 1, of the MRP). PR-6 is the most used road at this site and sees annual applications of magnesium chloride, as well as regular water treatments during the hot, dry months. The additional signs should have been installed on the primary road PR-5, which provides heavy truck access to the east side of the main stockpile areas, (See Plate 1). This road generally does not see regular applications of water, and coal accumulations (from gravity movement from the stockpiles) are constantly being run over by trucks. Hence, if speeds are not maintained at the 5 MPH limit, heavy concentrations of fugitive dust are thrown into suspension. The Permittee needs to install additional speed limit signs along primary road PR-5.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Several ponds including ponds "E" and "F" had snow covered bottoms. Snow melt runoff was visible in all others.

4.d Hydrologic Balance: Water Monitoring

The Permittee notified the Division on December 8, 2005 that the third quarter of 2005 surface water monitoring information for the Wildcat loadout was in the pipeline, ready for uploading. That information included UPDES monitoring for the sites six sediment ponds as well.

7. Coal Mine Waste, Refuse Piles, Impoundments

There were no compliance issues noted with the waste rock disposal area. Noncoal waste was not visible in the end-dumped piles.